


09894475.062701



09894475.062701




FIG. 2

A hand-drawn schematic diagram of a mechanical assembly. The diagram shows a cross-section of a structure with several labeled components:

- 302**: Points to the top horizontal surface of a large rectangular block on the left.
- 300**: Points to a small, shaded circular feature located at the corner where the top surface of the block meets a vertical edge.
- 315**: Points to the curved surface of the block immediately adjacent to the shaded feature 300.
- 304**: Points to a vertical edge or wall on the right side of the assembly.
- 310**: A double-headed horizontal arrow indicating the distance between the vertical edge of the block (where 300 is located) and the vertical wall 304.
- 306**: Points to the bottom vertical surface of the structure.

FIG 3A

090447 0004




FIG 3B

0904475.062701  
T02290 92445860




FIG 4A

A hand-drawn schematic diagram of a stepped profile. The profile consists of a top horizontal section, a vertical section, and a bottom horizontal section. The top horizontal section is labeled 402. The vertical section is labeled 404. The bottom horizontal section is labeled 406. A dashed line indicates a transition from the top horizontal section to the vertical section, labeled 450. The diagram is drawn with simple lines on a white background.

FIG 4B

09894475.062701




FIG 5